

Ship Name:	ABANT	Ship Type:	Bulk Carrier
IMO Number:	7364132	Flag:	Turkey
Date Detained:	06/28/2002	Class Society:	Det Norske Veritas
Port:	Mobile, Alabama	Company(s):	<u>Owners, Operators or Managers</u> Yukdiz Debiz Tasmaciligi

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0735 - Personal equipment - fire fighting	Supplied air breathing apparatus inoperable.
	0750 - Fire prevention	Fire detection units inoperable in engineering space.

Ship Name:	CARIB VISION	Ship Type:	Oil Tankship
IMO Number:	7636561	Flag:	Liberia
Date Detained:	06/11/2002	Class Society:	Russian Maritime Register of Shipping
Port:	San Juan, Puerto Rico	Company(s):	<u>Owners, Operators or Managers</u> Epps Shipping Co. Lipolar Management Ltd.

Deficiencies:	<u>Code - Category</u>	<u>Description</u>
	0740 - Pumps	Vessel's emergency fire pump is inoperative.
	1730 - Oily-water separating equipment	Vessel's Oily Water Separator is inoperative.
	2510 - Safety and environmental policy	Objective evidence indicated that there is a breakdown in the vessel's Safety Management System. Vessel to have an external ISM audit conduted. Provide a copy of the audit results to Marine Safety Office San Juan prior to departure.
	0799 - Other (Fire Fighting Equipment)	Four of five of the vessel's pick-up tubes for portable foam applicators were severely dry rotted and came apart when flexed.
	2099 - Other (SOLAS Related Operational Def.)	Emergency fuel cut-off valve for emergency generator day tank could not be released from outside the emegency generator room space because the pull cable was not connected.

Ship Name: **KAMACHATSKIY PROLIV**
IMO Number: **8228476**
Date Detained: **06/25/2002**
Port: **Jacksonville, Florida**

Ship Type: **Refrigerated Cargo Carrier**
Flag: **Panama**
Class Society: **Russian Maritime Register of Shipping**
Company(s): Owners, Operators or Managers
Shaft Maritime S.A.
Yugreftransflot Sevastopol

Deficiencies: Code - Category
1530 - Radar
0715 - Detection
2020 - Fire drills

2025 - Abandon ship drills

Description
ARPA/primary radar inoperable.
Fire detection system not functioning properly.
Crew unable to demonstrate proficiency in fire drill.

Crew unable to demonstrate proficiency in abandon drill.

Ship Name: **KIMBERLY**
IMO Number: **7381087**
Date Detained: **06/19/2002**
Port: **New Haven, Connecticut**

Ship Type: **Bulk Carrier**
Flag: **Saint Vincent and the Grenadines**
Class Society: **Bureau Veritas**
Company(s): Owners, Operators or Managers
Eastmark Associates Inc, United

Deficiencies: Code - Category
0987 - Bulkheads - cracking
0330 - Sanitary facilities

0730 - Appliances (general equipment)
0730 - Appliances (general equipment)

Description
Multiple holes in cargo bulkheads.
Crew restrooms unsanitary and medical toilet not working.

Firemain system holed in numerous spots on main deck starboard side in area of cargo holds.
Valves on fire stations on accomodation deck and boiler deck starboard side not seated properly

Ship Name: **LEVANTE**
IMO Number: **7720740**
Date Detained: **06/20/2002**
Port: **Mobile, Alabama**

Ship Type: **General Dry Cargo Ship**
Flag: **Cyprus**
Class Society: **Bureau Veritas**
Company(s): Owners, Operators or Managers
Candid Navigation Inc.
Apeldor Shipping Co. LTD

Deficiencies: Code - Category
2020 - Fire drills

2025 - Abandon ship drills

1270 - Doors

1740 - Oil discharge mon/contr

Description
Crew unable to demonstrate proficiency in a fire drill.

Crew unable to demonstrate proficiency in an abandon ship drill.

All watertight doors, gaskets and dogs are to be repaired as needed.

Automatic stopping device for oily water

system

separator inoperable.

Ship Name:	LOK PRAKASH	Ship Type:	Bulk Carrier
IMO Number:	8126769	Flag:	India
Date Detained:	06/06/2002	Class Society:	Lloyd's Register of Shipping
Port:	Long Beach, California	Company(s):	<u>Owners, Operators or Managers</u> The Shipping Corp. of India Ltd
Deficiencies:	<u>Code - Category</u> 2510 - Safety and environmental policy 1280 - Machinery space openings 1299 - Other (Load Lines) 1299 - Other (Load Lines)	<u>Description</u> Vessel not in compliance with ISM Code. Company not ensuring that appropriate corrective action is taken nor non-conformities are being reported with known cause. Machinery space openings not watertight. Hull in wasted condition. Excessive soft patches in engineroom.	

Ship Name:	MARIANIC K	Ship Type:	Bulk Carrier
IMO Number:	7919846	Flag:	Cyprus
Date Detained:	06/06/2002	Class Society:	Bureau Veritas
Port:	Newport News, Virginia	Company(s):	<u>Owners, Operators or Managers</u> Seabound Maritime Inc. blue sympathy shipping co
Deficiencies:	<u>Code - Category</u> 2545 - Reports/analysis of non-conformities, etc. 2525 - Masters responsibility and authority 2510 - Safety and environmental policy 1240 - Cargo and other hatchways 1240 - Cargo and other hatchways 1240 - Cargo and other hatchways 1240 - Cargo and other hatchways 1299 - Other (Load Lines)	<u>Description</u> No documentation could be provided indicating that non-conformities were drafted for the numerous cement patches and temporary repairs onboard the vessel. Master failed to report to the company the cargo hold area wastage problems in accordance with the Safety Management System. Objective evidence indicates there is a breakdown in the Safety Management System. Vessel ordered to conduct an external audit. Welds on port side corner brackets at crossdeck between no. 4, 5, and 6 cargo holds fractured. Unauthorized cement patches at no. 5 cargo hatch jacks. Unauthorized clad weld repair on crossdeck between no. 1 and no. 2 cargo holds. Fractures on no. 4, 5 and 6 cargo hold cable tunnels near crossdecks. Unauthorized inserts (4) in main deck between forepeak and no. 1 cargo hold.	

Ship Name:	SCM LIA	Ship Type:	Containership
IMO Number:	9223459	Flag:	Antigua and Barbuda
Date Detained:	06/23/2002	Class Society:	Germanischer Lloyd
Port:	Port Everglades, Florida	Company(s):	<u>Owners, Operators or Managers</u> W. bocksteigerl GMBH & Co.

Deficiencies:	<u>Code - Category</u> 2020 - Fire drills	<u>Description</u> Crew unable to demonstrate proficiency in a fire drill.
	0735 - Personal equipment - fire Fighting	Both firefighting outfits in poor condition.

Ship Name:	STARLIGHT	Ship Type:	Bulk Carrier
IMO Number:	7517014	Flag:	Cyprus
Date Detained:	06/14/2002	Class Society:	Lloyd's Register of Shipping
Port:	Baltimore, Maryland	Company(s):	<u>Owners, Operators or Managers</u> Interpleader Marien Company LTD. Navitas Compania Maritime S.A.

Deficiencies:	<u>Code - Category</u> 1299 - Other (Load Lines)	<u>Description</u> Wasted hole found in deck/tank top located in steering room port side in way in way of refrigeration space.
	1299 - Other (Load Lines)	Starboard side salt water skin valve lower in engine room holed and wasted.
	1299 - Other (Load Lines)	Fuel oil vent pipe located next to port side embarkation ladder holed.
	1250 - Covers (hatchways	Numerous hatch coaming brackets on all cargo holds fractured.
	1275 - Ventilators air pipes	Air vent pipe inside boatswain store holed and wasted.
	1299 - Other (Load Lines)	Deck wasted and holed in areas around base of deckhouse between #2 and #3 hold
	1240 - Cargo and other hatchways	Numerous fractures around hatch corner radius on cargo holds no. 1,2, 4 and 6.
	1240 - Cargo and other hatchways	Hole found in #5 hatch coaming on starboard side.

Ship Name: **THOMAS SELMER**

IMO Number: **8214061**

Date Detained: **06/01/2002**

Port: **Portland, Oregon**

Ship Type: **Bulk Carrier**

Flag: **Marshall Islands**

Class Society: **Germanischer Lloyd**

Company(s): Owners, Operators or Managers
SCC Shipping Company, Ltd.

Deficiencies: Code - Category
0610 - Lifeboats
2020 - Fire drills

1671 - Satellite EPIRB
406MHz/1.6GHz

0750 - Fire prevention

0740 - Pumps

1499 - Other (Prop. & Aux.
Machinery)

0330 - Sanitary facilities

1730 - Oily-water separating
equipment

Description
Prove proper operation of lifeboat davits.
Vessel crew unable to demonstrate proficiency
in a fire drill.

EPIRB inoperable.

Make repairs as original or provide class
approval for the missing fire boundary doors
to the engineroom.

Properly secure loose heat exchanger which is
vibrating wildly while in operation.

Repair/replace steam valve where missing
from the steam line to the lube-oil heater.

The crew was unable to produce the required
chemical for the vessel's installed MSD.

The oily water separator inoperable.

Ship Name: **WARSAW**

IMO Number: **7407013**

Date Detained: **06/10/2002**

Port: **Jacksonville, Florida**

Ship Type: **Bulk Carrier**

Flag: **Marshall Islands**

Class Society: **Bureau Veritas**

Company(s): Owners, Operators or Managers
SMT Ship Management & Transport Ltd.

Deficiencies: Code - Category
2545 - Reports/analysis of
non-conformities, etc.

1740 - Oil discharge mon/contr
system

0740 - Pumps

Description
No non-conformities are being used for
missing/inoperative equipment in
engineroom.
Oily water separator inoperative.

Unable to demonstrate proper operation of
emergency fire pump due to compartment
partially flooded.